

Typical Wet-Bag Pressures for Various Ceramics
Typical Wet-Bag Pressures for Various Ceramics

Ceramic Material	Pressure, MPa
Alumina	50-100
Silica	50-100
Zirconia	100-200
Silicon nitride	100-200
Silicon carbide	100-200
Spinel	300-400